



Quote valid for 90 days

November 11th, 2014

Cory Matthews
EMS Chief
Bryan Fire Department
Email: cmatthews@bryantx.gov

Quote# 8987C

Chief Matthews,

Per your request we are quoting remounting and refurbishing your Frazer Type I 12' Generator Powered Module, E-1613, onto a 2015 Chevrolet C3500 6.0L gasoline chassis. For your convenience all pricing has been itemized below.

2015 Chevrolet C3500 6.0L gasoline chassis (order red)	\$ 33,000.00
Granning air suspension	\$ 6,700.00
Remount of module (see below)	\$ 14,000.00
Optional items (see below)	\$ 123,825.00
HGAC Fee	\$ 600.00
Total	\$ 178,125.00

Remount of module includes:

- a) New black grille guard with (4) Whelen M4 series grille & intersect LEDs and (2) Federal Signal AS124 speakers
- b) New console with new Whelen 295SLSA1 siren
- c) Inspect all generator cabling, replace as needed
- d) New boot plate and boot
- e) New mounting rubber
- f) Rewire tail lights
- g) New under hood breakers
- h) Electrical check-out
- i) Add insulation to side and rear entry doors
- j) Replace entry door windows with double pane windows
- k) New weatherstripping and rivets for compartment and entry doors
- l) Replace all non-skid material on threshold(s)
- m) Stripe new chassis

Items included in above total:

Chassis Exterior:

Black Ranch Hand powder coated grille guard	\$	incl.
Furnish and install SS wheel covers in lieu of factory wheel covers	\$	350.00
Furnish & install (2) Whelen SA314B speakers in lieu of standard	\$	450.00
Furnish and install (4) Whelen M6 series grille & intersect split LEDs in lieu of standard (b/r-r/c-c/r-r/b)	\$	300.00
Furnish and install (2) extra Whelen M6 series red/amber split LEDs in front fenders	\$	600.00
Furnish & install Per-Lux fog lights centered on grill guard	\$	350.00

Striping and lettering on chassis \$ incl.

Chassis Interior:

Furnish and install Autovision auto-dimming rear view mirror replacement (ID 17544) w/ 3.5" RCD monitor built and terminate wiring to rear view back up camera \$ 950.00

Remove and reinstall (2) large aluminum map holders at the rear of console \$ 25.00

Remove and reinstall (2) high glove box holder on rear wall of truck cab \$ 25.00

Remove and reinstall your Frazer swivel onto a new extended mdt plate w/ computer cradle; hardwire your existing power supply battery hot \$ 225.00

Remove and reinstall your VHF self contained radio in the console; remove and reinstall old antenna on chassis roof and run new coax \$ 350.00

Furnish and install (2) Streamlight SL-20X LED flashlights w/ chargers, one on each side of console (ID 27650) (note: replicate installation method of last new) \$ 450.00

Remove and reinstall your Knox key secure in same location in new chassis cab; wire battery hot (customer to provide removal key loose at time of drop off) \$ 175.00

Furnish and install Whelen 295HFSC9 siren in lieu of standard \$ 225.00

add Tap '2' feature on siren \$ incl.

Console layout: Extended MDT plate – Traffic Advisor Control Head – 295HFSC9 Siren – Single Switch Panel – Radio – Radio \$ incl.

Furnish and install a Motorola remote mount radio head package (APX6500-HCM2) provided quote) in module to include: (1) remote mount head at the console w/ the speaker mounted on the rear wall of the truck cab, (1) remote mount head at the action wall with speaker location to be determined, (1) GPS antenna on roof of chassis (discuss this), (1) dual band antenna on roof of chassis (discuss this), and run new coax to both antennas; \$ 5,125.00

Remove and reinstall your Data Radio Gemini system w/ antennas mounted on the roof of the chassis; do not remove existing antennae as customer will provide new antennae; route associated data cables to the computer mount and wire system fail safe \$ 425.00

Module Exterior:

Strip, prime, and repaint module Chevy red to match chassis; replace riveted corner trim w/ new smooth trim, replace corner caps, replace marker lights, reuse existing doors and double pane windows that have been retrofitted by service, replace all compartment latches with new Cleveland standard (J236 keying on all doors), replace compartment and entry door hinges, replace J channel drip rails, and replace compartment bumpers \$ 6,000.00

Striping and lettering on module to match chassis \$ 2,700.00

3M Diamond grade fluorescent lime yellow conspicuity tape w/ translucent red overlay on entire rear including rear entry doors \$ 1,500.00

Add 4" 3M Diamond Grade white conspicuity strips to the interior panels of all applicable compartment and entry doors \$ 175.00

All clear lenses on emergency LEDs \$ incl.

All existing emergency lights will be replaced at their existing location w/exception of rear lower emergency signal which will shift downward on plating from AC retrofit; all removed lighting will be shipped loose \$ incl.

Furnish and install (8) Whelen M6 series red LED box lights w/ chrome converter flanges \$ 1,800.00

Furnish and install (5) Whelen M6 series LEDs on front wall (b-r-c-r-b) w/ chrome converter flanges \$ 1,125.00

Furnish and install (4) Whelen M6 series LEDs on the rear wall (R/B-A-A-B/R) w/ chrome converter flanges; note rear wall lowers are 700 series but will be able to be replaced with M6 lighting due to AC retrofit plate installation \$ 1,000.00

Furnish and install (1) Whelen M6 series gradient LED load light centered between amber LEDs on rear of module w/ chrome load light converter flange \$ 375.00

Remove and replace existing upper brake/tail/turn signals w/(2) Whelen M6 series red

BTT LEDs w/chrome converter flanges (w/colored lens)	\$	350.00
Furnish and install (2) M7 series red/amber split wheel well LEDs w/ chrome converter flanges	\$	100.00
Furnish and install (1) Whelen Tam 85 traffic advisor on rear of module with the control head in the console	\$	1,425.00
Replace 30 amp shore power receptacle w/ new twist lock style with pigtail adapter shipped loose	\$	225.00
Replace rear entry door grabbers	\$	50.00
Replace license plate light w/ new cast LED style	\$	50.00
Replace gas shock on rear backboard compartment door	\$	25.00
Furnish and install Onan 5.5kW generator w/ new fuel tank and fuel pump (ship loose old)	\$	5,000.00
Replace air conditioner w/ new Dometic self-contained A/C unit, make necessary interior and exterior modifications to accommodate including addition of AC retrofit plates on rear of module; include new breathe easy plenum with germicidal UV light protection and relocation of thermostat to action wall	\$	5,500.00
Modify O ₂ compartment to include a vertical divider and a shortened horizontal shelf	\$	250.00
Terminate existing shore power kill switch to new chassis	\$	incl.
Inspect and repair cracks on welds in rear backboard compartment	\$	incl.
Do not remove (2) SCBA brackets and 2 coat hooks in rear storage compartment	\$	N/C
Re-route chassis exhaust to exit under long lower storage	\$	incl.
Furnish and install Voyager back up camera mounted on rear of module	\$	550.00
Replace Treadbrite on front corner, wheel wells, and at rear of module	\$	825.00
Remove and replace existing back up lamps and rear BTT signals w/ new LED 4" round fixtures mounted in the Treadbrite	\$	425.00
Replace entire rear bumper w/ new style w/ cast end caps (ship old loose)	\$	850.00
Replace single outer most roller and strap in the O ₂ compartment	\$	150.00
Add (2) 6 pt harness attachments w/ appropriate plating and support at attachment points at the forward end of the squad bench and at the CPR seat	\$	2,200.00
Add netting at front of squad bench to ceiling (like last)	\$	1,650.00

Module Interior:

Replace floor with Alucabond subfloor and Lonseal vinyl floor, reuse existing powder coated aluminum O ₂ box, replace thresholds and add non-skid tape on top, install new cot plates (review this at check in)	\$	3,000.00
Remove and reinstall 2 high "D" cylinder holder in front I/O facing rear (w/ floor replacement)	\$	Incl.
Terminate existing module door locks to chassis door lock controls and add new electronic keypad on d/s door of chassis; ensure door lock controls function off of key fob as well; replace existing actuators w/ new design for Cleveland latches	\$	750.00
Do not remove (2) large aluminum map holders on side of front I/O	\$	N/C
Replace ribbed rubber on shelf and floor of front I/O (discard old)	\$	50.00
175-3 single position cot mount	\$	incl.
Replace side entry door hold-open spring w/ new gas shock and accompanying grey head knocker	\$	250.00
New ash grey Wise corner trim in module	\$	300.00
Replace large acrylic holder aft of CPR seat	\$	250.00
Furnish and install new ash grey Wise soft cushion captain's chair w/ built-in child safety seat and 3 pt belt (ship loose old)	\$	1,325.00
Replace polycarbonate glass (Lexan) at all cabinets throughout the module	\$	725.00
Furnish and ship loose (1) LifePak LP15 monitor/defib as requested by customer through quote #1-270043991 (estimated pricing based upon projected pricing increases by manufacturer)	\$	38,000.00
Furnish and ship loose (1) Zoll Autopulse w/ 2 year extended warranty as requested by customer through quote 160846 v:1 (estimated pricing based upon projected		

pricing increases by manufacturer)	\$	18,800.00
Stryker Power Pro XT w/ charger and 3 batteries w/ a smart charger mounting bracket (estimated pricing based upon projected pricing increases by manufacturer)	\$	16,050.00

Items for your consideration (not included in above total):

*Replace existing power supply with new Lambda power supply	\$	1,350.00
Furnish and install (2) 3 high glove box holders (1 on side of action wall cabinet and 1 above front I/O); (note if these are present during check in)	\$	300.00
Add removable O ₂ bottle holder to Stryker Power Pro XT	\$	200.00
Add 2 stage IV pole to Stryker Power Pro XT	\$	275.00
Add head end storage to Stryker Power Pro XT	\$	150.00

*Determination of need for replacement will be made during final QC checkout under full power load

All pricing is F.O.B. Houston.

Per TMVCC we are quoting this through our licensed franchise dealer, Knapp Chevrolet.

Please make your purchase order out to Knapp Chevrolet (P.O. Box 4179, Houston, TX 77210). Please email a copy of your purchase order and this quote to Bob Flanders with Knapp Chevrolet at bflanders@knappchevy.com and to Adam Fischer at sales@frazerbilt.com.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Laura Richardson
Frazer, Ltd.

LGR:AD



November 11th, 2014

Quote valid for 90 days

Cory Matthews
EMS Chief
Bryan Fire Department
Email: cmatthews@bryantx.gov

Quote #8988C

Chief Matthews,

Per your request we are quoting remounting and refurbishing your Frazer Type I 12' Generator Powered Module, E-1348 / X-613, onto a 2015 Chevrolet C3500 6.0L gasoline chassis. For your convenience all pricing has been itemized below.

2015 Chevrolet C3500 6.0L gasoline chassis (order red)	\$ 33,000.00
Granning air suspension	\$ 6,700.00
Remount of module (see below)	\$ 14,000.00
Optional items (see below)	\$ 117,500.00
HGAC Fee	\$ 600.00
Total	\$ 171,800.00

Remount of module includes:

- a) New black grille guard with (4) Whelen M4 series grille & intersect LEDs and (2) Federal Signal AS124 speakers
- b) New console with new Whelen 295SLSA1 siren
- c) Inspect all generator cabling, replace as needed
- d) New boot plate and boot
- e) New mounting rubber
- f) Rewire tail lights
- g) New under hood breakers
- h) Electrical check-out
- i) Add insulation to side and rear entry doors
- j) Replace entry door windows with double pane windows
- k) New weatherstripping and rivets for compartment and entry doors
- l) Replace all non-skid material on threshold(s)
- m) Stripe new chassis

Items included in above total:

Chassis Exterior:

Black Ranch Hand powder coated grille guard	\$	incl.
Furnish and install SS wheel covers in lieu of factory wheel covers	\$	350.00
Furnish & install (2) Whelen SA314B speakers in lieu of standard	\$	450.00
Furnish and install (4) Whelen M6 series grille & intersect split LEDs in lieu of standard (b/r-r/c-c/r-r/b)	\$	300.00
Furnish and install (2) extra Whelen M6 series red/amber split LEDs in front fenders	\$	600.00

Furnish & install Per-Lux fog lights centered on grill guard	\$ 350.00
Striping and lettering on chassis	\$ incl.

Chassis Interior:

Remove and reinstall your existing back up camera system w/ monitor in rear view mirror	\$ 450.00
Remove and reinstall your Frazer swivel onto a new extended mdt plate w/ computer cradle; hardwire your existing power supply battery hot	\$ 225.00
Remove and reinstall your VHF self contained radio in the console; remove and reinstall old antenna on chassis roof and run new coax	\$ 350.00
Remove and reinstall double glove holder on rear wall of chassis	\$ 25.00
Remove and reinstall existing dual map holder on rear of console	\$ 25.00
Remove and reinstall your Knox key secure in same location in new chassis cab; wire battery hot (customer to provide removal key loose at time of drop off)	\$ 175.00
Furnish and install (2) Streamlight SL-20X LED flashlights w/ chargers, one on each side of console (ID 27650) (note: replicate installation method of last new)	\$ 450.00
Furnish and install Whelen 295HFSC9 siren in lieu of standard	\$ 225.00
Add Tap '2' feature on siren	\$ incl.
Remove and reinstall existing traffic advisor control head in console; terminate to TA bar of rear of module	\$ 275.00
Console layout: Extended MDT plate – Traffic Advisor Control Head – 295HFSC9 Siren – Single Switch Panel – Radio – Radio	\$ incl.
Furnish and install a Motorola remote mount radio head package (APX6500-HCM2) provided quote) in module to include: (1) remote mount head at the console w/ the speaker mounted on the rear wall of the truck cab, (1) remote mount head at the action wall with speaker location to be determined, (1) GPS antenna on roof of chassis (discuss this), (1) dual band antenna on roof of chassis (discuss this), and run new coax to both antennas:remove and ship loose existing radio system (not 800 MHZ)	\$ 5,125.00

Module Exterior:

Strip, prime, and repaint module Chevy red to match chassis; replace riveted corner trim w/ new smooth trim, replace corner caps, replace marker lights, reuse existing doors and double pane windows that have been retrofitted by service, replace all compartment latches with new Cleveland standard (J236 keying on all doors), replace compartment and entry door hinges, replace J channel drip rails, and replace compartment bumpers	\$ 6,000.00
Striping and lettering on module to match chassis	\$ 2,700.00
3M Diamond grade fluorescent lime yellow conspicuity tape w/ translucent red overlay on entire rear including rear entry doors	\$ 1,500.00
Add 4" 3M Diamond Grade white conspicuity strips to the interior panels of all applicable compartment and entry doors	\$ 175.00
All clear lenses on emergency LEDs	\$ incl.
All existing emergency lights will be replaced at their existing location w/exception of rear lower emergency lights which will shift downward on plating from AC retrofit; all removed lighting will be shipped loose	\$ incl.
Furnish and install (8) Whelen M6 series red LED box lights w/ chrome converter flanges	\$ 1,800.00
Furnish and install (5) Whelen M6 series LEDs on front wall (B-R-C-R-B) w/ chrome converter flanges	\$ 1,125.00
Furnish and install (4) Whelen M6 series LEDs on the rear wall (R/B-A-A-B/R) w/ chrome converter flanges; note rear wall lowers are 700 series but will be able to be replaced with M6 lighting due to AC retrofit plate installation	\$ 1,000.00
Furnish and install (1) Whelen M6 series gradient LED load light centered between amber LEDs on rear of module w/ chrome load light converter flange	\$ 375.00
Remove and replace existing upper brake/tail/turn signals w/(2) Whelen M6 series red	

BTT LEDs w/chrome converter flanges (w/colored lenses)	\$	350.00
Furnish and install (2) M7 series red/amber split wheel well LEDs w/ chrome converter flanges	\$	100.00
Remove and reinstall your existing traffic advisor bar on rear of module	\$	incl.
Replace 30 amp shore power receptacle w/ new twist lock style with pigtail adapter shipped loose	\$	225.00
Replace rear entry door grabbers	\$	50.00
Replace license plate light w/ new cast LED style	\$	50.00
Replace gas shock on rear backboard compartment door	\$	25.00
Furnish and install Onan 5.5kW generator w/ new fuel tank and fuel pump (ship loose old)	\$	5,000.00
Replace air conditioner w/ new Dometic self-contained A/C unit, make necessary interior and exterior modifications to accommodate including addition of AC retrofit plates on rear of module; include new breathe easy plenum with germicidal UV light protection and relocation of thermostat to action wall	\$	5,500.00
Modify O ₂ compartment to include a vertical divider and a shortened horizontal shelf	\$	250.00
Terminate existing shore power kill switch to new chassis	\$	incl.
Inspect and repair cracks on welds in rear backboard compartment	\$	incl.
We are not to remove (2) SCBA brackets and 2 coat hooks in rear storage compartment	\$	N/C
Re-route chassis exhaust to exit under long lower storage	\$	incl.
Remove and reinstall your traffic advisor bar on rear of module	\$	incl.
Replace Treadbrite on front corner, wheel wells, and at rear of module	\$	825.00
Remove and replace existing back up lamps and rear BTT signals w/ new LED 4" round fixtures mounted in the Treadbrite	\$	425.00
Replace entire rear bumper w/ new style w/ cast end caps (ship old loose)	\$	850.00
Replace single outer most roller and strap in the O ₂ compartment	\$	150.00

Module Interior:

Terminate existing module door locks to chassis door lock controls and add new electronic keypad on d/s door of chassis; ensure door lock controls function off of key fob as well; replace existing actuators w/ new design for Cleveland latches	\$	900.00
Do not remove (2) large aluminum map holders on side of front I/O	\$	N/C
Replace ribbed rubber on shelf and floor of front I/O (discard old)	\$	50.00
Do not add lip on floor of front I/O (has roll up door configuration)	\$	N/C
175-3 single position cot mount	\$	incl.
Replace side entry door hold-open spring w/ new gas shock and accompanying grey head knocker	\$	250.00
New ash grey Wise corner trim in module	\$	300.00
Replace large acrylic holder aft of CPR seat	\$	250.00
Furnish and install new ash grey Wise soft cushion captain's chair w/ built-in child safety seat and 3 pt belt (ship loose old)	\$	1,325.00
Remove and reinstall 2 high "D" cylinder holder in front I/O facing rear (w/ floor replacement)	\$	Incl.
Replace floor with Alucabond subfloor and Lonseal vinyl floor, reuse existing powder coated aluminum O ₂ box, replace thresholds and add non-skid tape on top, install new cot plates (review this at check in)	\$	3,000.00
Replace polycarbonate glass (Lexan) at all cabinets throughout the module	\$	725.00
Furnish and ship loose (1) LifePak LP15 monitor/defib as requested by customer through quote #1-270043991 (estimated pricing based upon projected pricing increases by manufacturer)	\$	38,000.00
Furnish and ship loose (1) Zoll Autopulse w/ 2 year extended warranty as requested by customer through quote 160846 v:1 (estimated pricing based upon projected pricing increases by manufacturer)	\$	18,800.00
Stryker Power Pro XT w/ charger and 3 batteries w/ a smart charger mounting bracket (estimated pricing based upon projected pricing increases by manufacturer)	\$	16,050.00

Items for your consideration (not included in above total):

*Replace existing power supply with new Lambda power supply	\$	1,350.00
Furnish and install (2) 3 high glove box holders (1 on side of action wall cabinet and 1 above front I/O); (note verify these are here during check in)	\$	300.00
Add removable O ₂ bottle holder to Stryker Power Pro XT	\$	200.00
Add 2 stage IV pole to Stryker Power Pro XT	\$	275.00
Add head end storage to Stryker Power Pro XT	\$	150.00
Remove and reinstall your Data Radio Gemini system w/ antennas mounted on the roof of the chassis; do not remove existing antennae as customer will provide new antennae; route associated data cables to the computer mount and wire system fail safe	\$	425.00

*Determination of need for replacement will be made during final QC checkout under full power load

All pricing is F.O.B. Houston.

Per TMVCC we are quoting this through our licensed franchise dealer, Knapp Chevrolet.

Please make your purchase order out to Knapp Chevrolet (P.O. Box 4179, Houston, TX 77210). Please email a copy of your purchase order and this quote to Bob Flanders with Knapp Chevrolet at bflanders@knappchevy.com and to Adam Fischer at sales@frazerbilt.com.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Laura Richardson
Frazer, Ltd.

LGR:AD

CALDWELL COUNTRY FORD-CHEVROLET

800 HWY 21 E. CALDWELL, TEXAS 77836

BUYBOARD 430-13

End User: CITY OF BRYAN

Caldwell Rep: ALAN WILEY 254 865-9112

Contact: BOBBY WALKER 979-209-5905

Date: 29-Oct-14

Product Description: CHEVROLET SUBURBAN

A. Bid Series: 22

A. Base Price: \$ **34,585.00**

B. Published Options [Itemize each below]

Code	Options	Bid Price	Code	Options	Bid Price
CC	2015 2WD SUBURBAN	\$ 2,447.00	VAV	ALL WEATHER FLOOR MATS	\$ 195.00
15906	LS PREFERRED EQUIPMENT	INCL	VLI	REAR CARGO MAT	\$ 75.00
LS	CLOTH BUCKET SEATS	INCL	TGK	SPECIAL PAINT	\$ 285.00
	CARPET	INCL	5T4	VICTORY RED PAINT	\$ 190.00
	5.3L V8 AUTOMATIC	INCL			
				BODY SIDE MOLDING NOT	NOTE
				RED PAINT AVAILABLE	NOTE
				MUD DEFLECTORS NO	NOTE
				LONGER FACTORY AVAILABLE	NOTE
				ESTIMATED DELIVERY IN	DELIVERY
NHT	MAX TRAILER TOW PACKAGE	\$ 395.00		90-150 DAYS WITH SPECIAL	
	TRAILER BRAKE CONTROLLER	INCL		VICTORY RED PAINT	

Total of B. Published Options: \$ 3,587.00

C. Unpublished Options [Itemize each below, not to exceed 25%]

\$= 6.4 %

Options	Bid Price	Options	Bid Price
PLEASE FAX PURCHASE ORDERS TO	NOTE	METRO FIRE LETTERING	\$ 1,870.00
254 865-9118		DONE IN BRYAN	NOTE
alan@caldwellcountry.com	E-MAIL	GRILL GUARD INSTALLED BY	\$ 575.00
		TEXAS TRUCK RIGGINS	NOTE
		SUBURBAN WILL BE DELIVERED TO	NOTE
		CITY OF BRYAN FLEET DEPARTMENT	NOTE
		CITY OF BRYAN FLEET TO MAKE	NOTE
		ARRANGEMENTS FOR METRO FIRE	NOTE
		AND TEXAS TRUCK RIGGINS	NOTE
		INSTALLATION	NOTE

Total of C. Unpublished Options: \$ 2,445.00

D. Contract Price Adjustment: _____

E. Delivery Charges: 0

F. Total of A + B + C + D + E = F

\$ **40,617.00**

G. Quantity Ordered 1 x F =

\$ **40,617.00**

H. BUYBOARD FEE PER PURCHASE ORDER

\$ **400.00**

I. Non-Equip Charges & Credits _____

J. TOTAL PURCHASE PRICE INCLUDING BUYBOARD FEE

\$ **41,017.00**