



May 31, 2016

Mr. Cory Matthews
 EMS Chief
 Bryan Fire Department
 Email: cmatthews@bryantx.gov

Quote # 10780

Chief Matthews,

Per your request we are quoting remounting and refurbishing your Frazer Type I 12'4" taller Generator Powered Module (E-1859) onto a 2016/2017 Chevrolet C3500 6.0L gasoline chassis, 84" CA (Ordered White) with a Granning air suspension system. For your convenience all pricing has been itemized below.

Frazer Type I 12'4" taller Generator Powered Module (E-1859)		
2016/2017 Chevrolet C3500 6.0L gasoline chassis, 84" CA (Ordered White)	\$	35,750.00

Granning air suspension system	\$	7,250.00
--------------------------------	----	----------

Remount of Module (see Incl. items below)	\$	18,000.00
Chassis Exterior Upgrades	\$	9,550.00
Chassis Interior Upgrades	\$	17,900.00
Module Exterior Upgrades	\$	50,625.00
Module Interior Upgrades	\$	55,900.00
HGAC fee	\$	600.00
	\$	195,575.00

Items included in above total:

Chassis Exterior Upgrades:

- | | | |
|--|----|--------|
| 1 . Items included in remount fee: | \$ | Incl. |
| a) Ranch Hand powder coated grille guard | | |
| b) (2) Whelen M6 red/clear split grille LEDs with clear lenses in lieu of standard M4 LEDs | \$ | 150.00 |
| <i>Layout: Red/Clear - Clear/Red</i> | | |

c) (2) Whelen M6 red/clear split intersect LEDs with clear lenses & 45 degree brackets in lieu of standard M4 LEDs	\$	150.00
<i>Layout: Blue/Red - Red/Blue</i>		
e) (2) Whelen SA315P speakers in lieu of standard	\$	incl.
e) Frazer aluminum rear window pass through plate		
<i>Note - install sliding rear window</i>		
g) (2) Mega fuses with new wiring		
h) New mounting rubber		
i) New tie downs & spacers		
j) VHB Tape		
k) Furnish & install back-up alarm & kill relay for Chevy C3500		
<i>Note - install backup alarm kill relay</i>		
l) Mud flaps		
m) This unit needs a state inspection		
n) Make old chassis road ready - customer will pick up (TBD)		
1. Install rear mud flaps on chassis		
2. Install rear BTT lights		
3. Reinstall existing air suspension compressor from front I/O onto old chassis		
4. Remove license plate on rear of module and keep with old chassis		
o) Fuel with gasoline to verify fuel flow		
p) Issue temporary license plate		
q) Wash Unit		
r) Unit will be picked up by the customer		
s) Stripe new chassis to match module		
t) Re-route chassis exhaust to exit under long lower storage compartment		
u) Furnish & install Stainless steel wheel covers		
2 . Furnish & install ArcRite running boards on chassis	\$	850.00
4 . Chassis has single color paint scheme; Candy Apple Red - FLNA 3047	\$	5,000.00
5 . Furnish & install Hella fog lights on the grille guard w/ switch on console	\$	400.00
6 . Furnish & install (2) extra Whelen M6 series red/amber split LEDs on front fenders (red to front)	\$	500.00
7 . Furnish & install dual Buell 10" and 12" air horns through the front bumper, and compressor mounted in the electrical compartment	\$	1,700.00
<i>Note – install momentary switch at the console on blank space forward of the siren to the left of the MDT swivel.</i>		

8 . After market vinyl seats in truck cab- Pattern: Marlin, Color: MRL-3226 Blackbeard	\$	800.00
	\$	9,550.00

Chassis Interior Upgrades:

9 . Furnish & install pinned powder coated aluminum six position console:	\$	Incl.
a) Slot 1 – Furnish & install MDT plate (extended) with holes moved as far forward and to the right as possible - no swivel - without a genset fuel gauge	\$	50.00
Note - Remove and reinstall your Frazer swivel onto extended MDT plate		
b) Slot 2 – Remove & reinstall Traffic advisor control head		
Note - terminate to existing traffic advisor on rear wall of module		
c) Slot 3 – Furnish & install Whelen 295HFSC9 siren in lieu of standard with Tap 2 w/ mic on P/S of console slot #2	\$	250.00
d) Slot 4 – Single Switch Panel		
Switch layout – Primary, Secondary, Side Scene, Side Scene, Front Scene, Fog Lights, Rear Load, Interior Lights, Start/Stop		
e) Slot 5 - Radio plate 2398		
f) Slot 6 - Radio plate 2399		
10 . Furnish & install (1) large aluminum map holder on rear of console	\$	200.00
11 . Remove & reinstall (2) Streamlight SL-20X LED flashlight chargers, one on each side of console towards the front at an angle	\$	300.00
Note - wired battery hot		
12 . Furnish & install Knox Key Secure w/ WiFi on floor in front of console towards D/S - facing up	\$	1,750.00
Note - wired battery hot		
13 . Remove and reinstall 2 high glove box holder on rear wall of chassis	\$	100.00
14 . Remove and re-install Motorola APX6500 remote head in console slot 5	\$	300.00
a) Remove & reinstall speaker on chassis floor in front of console		
b) Remove & reinstall mic on driver side of slot 1		
c) Wire radio battery hot		
15 . Furnish & install Motorola APX 4500 VHF radio head in console slot 6	\$	1,000.00
a) Furnish & install mic on D/S of slot 2		
b) Run radio cables to base in electrical compartment		
16 . Furnish & install Havis docking station for Panasonic Toughbook laptops with power supply and dual high gain antenna, Lind power supply, Panasonic Toughbook CF-31 and CF-19 per customer provided quote Q-140353. (Note – drop ship computers directly to customer)	\$	12,500.00
17 . Remove and reinstall power supply inside console	\$	150.00
Note - wire battery hot		
18 . Remove and reinstall Tremco anti-theft system in the chassis cab with foot switch under drivers side mat and the module under drivers side of dashboard	\$	400.00
19 . Remove Cradlepoint router from rear wall of chassis and reinstall on rear wall of new chassis behind driver seat, wire ignition hot	\$	400.00
20 . Remove & reinstall existing back-up camera monitor in new chassis	\$	500.00

Note - reconnect to existing back-up camera

\$ 17,900.00

Module Exterior Upgrades:

21 . Items included in remount fee:

\$ Incl.

- a) Install new ignition & fail safe solenoids on electrical shelf
- b) Full electrical check
- c) Furnish & install (2) 4" round red LED lower B/T/T's and (2) 4" round lower clear back up lights
- d) New passthrough rubber boot
- e) Replace all door compartment bumpers
- f) Replace weather stripping
- g) New ribbed rubber in all applicable compartments
- h) Replace existing halogen compartment lights w/ LED flex strip lighting
 - (1) 43" LED flex light along the forward wall, next to the insert of the O2 compartment
 - (1) 55" LED flex light along the ceiling, next to the insert of the long lower storage compartment
 - (1) 12" LED flex light along the forward wall, next to the insert of the radio/storage compartment
 - (1) 36" LED flex light along the rear wall, next to the insert of the rear storage compartment
 - (1) 36" LED flex light along the front wall lasco, next to the insert of the front I/O
- i) Zero clearance behind side main entry step well
- j) Zero clearance inside lower front I/O compartment
- k) Verify front and rear wall skins have 10ga Black ground wire terminated to roof frame
- l) This unit needs to be weighed and a weight slip provided to the customer
- m) Replace marker lights (discard old)
- n) Furnish & install wheel well guard
- o) Install new factory fuel guards (discard old)
- p) Frazer key fob
- q) Furnish & install genset shutdown circuit w/ acknowledge switch at rear door switch panel

22 . Striping & lettering to match existing fleet (See Kelly)	\$	2,650.00
23 . Conspicuity on the entire rear of the module in a chevron pattern; FLUORESCENT YELLOW/GREEN base - RED translucent overlay	\$	1,500.00
24 . Removal of existing conspicuity on rear of module	\$	600.00
25 . Furnish and install 4" 3M diamond grade white conspicuity strips on interior panels of side and rear entry doors	\$	150.00
26 . Furnish and install the following decals:	\$	Incl.
a) Install CO stickers in three (3) locations		
b) Install one (1) NO SMOKING sticker on dash and ship one (1) loose		
27 . Strip, prime, and repaint 12'4" taller module Candy Apple Red - FLNA 3047	\$	15,750.00
a) Furnish & install painted corner caps on module		
b) Replace compartment and entry door latches (Eberhard)		

- c) J236 keys & 102 keys
- d) Ship loose all existing emergency lighting:
- e) Rear entry corner guards
- f) Install new drip rails on the following:
 - 1. Side entry door
 - 2. Rear entry doors
 - 3. Rear backboard compartment
- g) Furnish & install gas shock on long lower storage compartment (discard existing)
- h) Furnish and install O2 compartment vent
- i) Install new O2 compartment insert threshold (discard old)
- j) Replace side entry door gas shock with new (discard existing)
- k) Install new side entry door grab rail
- l) Install new rear entry door grab rails
- m) Replace entry door windows with double pane windows

- n) Remove and reinstall Voyager back up camera on rear wall; run cable to monitor in chassis cab
- o) Remove & reinstall the following module roof mounted antennae's:
 - Location #1: Black whip antenna
 - Location #2: Black cylinder antenna
 - Location #3: Large black cylinder antenna
- p) Remove & reinstall traffic advisor on rear wall of module
- 28 . Furnish & install new doors on the following (discard old): \$ Incl.
 - a) O2 compartment
 - b) Radio compartment
 - c) Long lower storage compartment
 - d) Rear storage compartment
 - e) Rear passenger's side entry door
 - f) Rear driver's side entry door
 - g) Side entry door
 - h) Generator compartment
 - i) Front I/O compartment
 - j) A/C compartment
 - k) Electrical compartment
 - l) Rear backboard compartment
- 29 . Furnish & install new panels on the following new doors: \$ Incl.
 - a) O2 compartment
 - b) Radio compartment
 - c) Long lower storage compartment
 - d) Rear storage compartment
 - e) Rear passenger's side entry door
 - f) Rear driver's side entry door
 - g) Side entry door
 - h) Front I/O compartment
 - i) A/C compartment
 - j) Electrical compartment
 - k) Rear backboard compartment
- 30 . Furnish & install new hinges on the following doors (discard old): \$ Incl.
 - a) O2 compartment
 - b) Radio compartment
 - c) Long lower storage compartment
 - d) Rear storage compartment
 - e) Rear passenger's side entry door
 - f) Rear driver's side entry door
 - g) Side entry door
 - h) Generator compartment
 - i) Front I/O compartment
 - j) A/C compartment
 - k) Electrical compartment
 - l) Rear backboard compartment
- 31 . Furnish & install new style actuators and reconnect electric locks to chassis for front I/O side and rear entry doors, install new contacts for doors for existing electric locks \$ 1,500.00

Note - Key fob will work chassis door locks only. Factory door switch will work all locks

32 .	ALL EMERGENCY LIGHTING TO HAVE CLEAR LENSES		
33 .	Furnish & install (8) Whelen M9 series red corner box lights w/ standard chrome flanges	\$	2,200.00
34 .	Furnish & install (5) Whelen M6 series on front wall w/ converter flanges <i>Front Layout: Blue, Red, Clear, Red, Blue</i>	\$	1,000.00
35 .	Furnish & install (4) Whelen M6 series on rear wall w/ converter flanges <i>Rear layout: Red/Blue, Amber, Amber, Blue/Red</i>	\$	850.00
36 .	Furnish & install (1) Whelen M6 Gradient load light w/ converter flange on rear of module <i>Note - Come on with reverse, and (2) three-way switches: one at console, one at rear doors</i>	\$	325.00
37 .	Furnish & install (2) Whelen M6 red B/T/T w/ converter flanges on rear wall	\$	300.00
38 .	Furnish and install (2) Whelen M6 LED split amber/red wheel well lights with chrome converter flanges <i>Note - Red to front</i>	\$	450.00
39 .	Furnish & install (2) FRC 900 series Spectra LED side scene lights in standard location, wired to 2 switches <i>Note - convert wiring in electrical compartment to 12V; add plating to existing location on passenger's side</i>	\$	2,000.00
40 .	Furnish & install (1) Whelen Pioneer Plus dual panel Super-LED floodlight on the front wall with ON/OFF switch at the console	\$	2,100.00
41 .	Furnish and install new 5.5kW generator and tie into factory chassis tank <i>Note – Please remove generator prior to delivery of unit to Frazer</i>	\$	7,500.00
42 .	Replace license plate holder w/ new Cast LED license plate holder	\$	100.00
43 .	Furnish & install new rear entry door grabbers, discard existing	\$	100.00
44 .	Replace entire rear bumper (discard existing)	\$	700.00
	a) Driver side bumper cap		
	b) Center step		
	c) Passenger side bumper cap		
	d) Driver & passenger side dock bumper		
	e) Center bumper strip		
45 .	Furnish & install treadbrite for the following (discard old):	\$	900.00
	a) Driver's & Passenger's side front corner panels		
	b) Passenger's side wheel well panel		
	c) Driver's side wheel well panel round filler guards		
	d) Driver side rear panel with (2) 4" round light cut outs		
	e) Passenger side rear panel with (2) 4" round light cut outs		
	n) Install rear entry threshold		
46 .	Furnish & install new Meltric single 30A twist lock shore power receptacle on driver's side front corner w/ pigtail shipped loose, (discard existing)	\$	750.00

47 .	Terminate existing shore power ignition kill switch in electrical compartment to new chassis	\$	100.00
48 .	Furnish & install new Lambda power supply (discard existing)	\$	1,500.00
49 .	Remove raised floor of the rear storage compartment (from split system A/C), and make floor flat	\$	600.00
50 .	Furnish & install 1"x2" angle on the roof of the rear storage compartment with (2) double coat hooks (coats will need latching mechanism to keep items from falling)	\$	150.00
	<i>Note - discard existing coat hooks on the rear & front wall</i>		
51 .	Remove & reinstall (2) SCBA brackets in rear storage compartment onto 6" flat bars in the back corners of the compartment 10" off the floor of the compartment.	\$	400.00
52 .	Furnish and install new Motorola VML 750 LTE modem in electrical compartment wire ignition hot	\$	2,500.00
	<i>Note - Ship loose existing Gemini data radio & all wiring from electrical compartment</i>	\$	100.00
	<i>Note - This device has three antennas that run to the roof and one Ethernet cable that runs to the MDT docking station. It does not connect to the other router.</i>		
53 .	Furnish & install Motorola APX 4500VHF radio base in electrical compartment	\$	2,000.00
	a) Furnish & install VHF antenna on module roof		
	b) Wire battery hot		
	c) Ship loose existing VHF radio base & antenna		
54 .	Furnish & install 3M-GTT Opticom on the front wall - discuss switching	\$	1,850.00
		\$	50,625.00

Module Interior Upgrades:

55 .	Items included in remount fee:	\$	incl.
	a) Replace all non-skid material on threshold(s) with 3M non-skid material		
	b) Complete detail of module interior:		
	Clean & wipe down lasco walls		
	Clean & wipe down floor of module		
	Clean & wipe down exterior & interior of cabinets		
	Clean & wipe down compartments and shelves		
	c) Air filter		
	d) Reattach any loose cushion magnets		
56 .	Furnish & install Ash grey wise trim (discard existing arm knockers)	\$	350.00
57 .	Replace floor with Alucabond subfloor and Lonseal vinyl floor - Lonplate II (gunmetal) (discard existing)	\$	3,300.00
	a) Remove & reinstall existing powder coated O2 box		
	b) Replace thresholds (discard existing)		
	c) Furnish & install cot mount & hook for a Stryker Performance-Pro XT/Power-Pro XT/MX-Pro 175-3 single position mount (discard existing)		
	d) Remove and reinstall 2 high "D" cylinder holder in front I/O next to divider facing rear entry doors		
58 .	Furnish and install new Wise captains chair with child safety seat & 3pt. harness, and new swivel in existing location (discard existing)	\$	1,500.00

59 .	Replace air conditioner w/ new Dometic self-contained A/C unit including compartment and discard existing A/C system; This includes making necessary modifications not limited to:	\$	7,500.00
	<i>Note - please remove A/C prior to drop-off at Frazer</i>		
	a) Interior cladding		
	b) Interior intake register		
	c) Interior vents		
	d) Install thermostat on A/C access panel (standard location)		
	e) A/C access panel		
	f) Relocation of (2) emergency rear lights with painted A/C retrofit plating		
	g) Round air vent on access panel		
	h) A/C exhaust vent		
	i) Duct box		
	j) Breathe easy plenum with germicidal UV light protection		
	k) Air filter		
	l) Extended Warranty		
	m) Thermostat Wire		
60 .	Modify the front I/O so AutoPulse device can be stored on its end, cut down shelf and add vertical divider	\$	650.00
61 .	Drop ship (2) Scott Air-Pak's AP-75 and carbon cylinders	\$	13,500.00
62 .	Drop-Ship AutoVent 3000 with carrying case	\$	4,500.00
63 .	Drop ship (1) Zoll Autopulse with 2 year extended warranty as requested by customer through quote #160846v:1 (estimated pricing based upon projected pricing increases by manufacturer)	\$	19,500.00
64 .	Furnish & install Knox Medvault with wifi in the corner area - includes running DC	\$	2,700.00
	<i>Note - wired battery hot</i>		
65 .	Furnish & install (8) Grote LED interior ceiling lights (discard existing lights)	\$	2,400.00
	<i>Note - Standard interior light switching;</i>		
	<i>Note - Remove and reinstall ceiling raceway covers for installation of new interior lights</i>		
	a) Driver's side front single LED on a 3 way switch to the HIGH setting		
	b) ON/OFF interior light switch at the console that controls the front driver's side interior LED only		
	c) ON/OFF interior light switch at the action wall that controls the front driver's interior LED only		
	d) HIGH/OFF/LOW interior light switch at the action wall that controls all but one of the interior LED's		
		\$	55,900.00
Additional items for your consideration:			
1 .	Furnish & install new traffic advisor with control head in console	\$	1,400.00
2 .	Furnish & install replacement rearview mirror with a built in 3.5" monitor	\$	1,050.00
	a) Reconnect to back up camera on rear wall		
3 .	Furnish & install antenna's & coaxes for all existing (discard existing antenna's and coaxes) - pricing will depend on exact antenna's present at time of check-in	\$	1,000.00

Terms and Conditions

- 1 . Quote valid for 90 days.
- 2 . All pricing is F.O.B Houston.
- 3 . Payment for the entire purchase is due upon receipt & acceptance of your completed unit.
- 4 . Please remove your Onan generator prior to remount delivery at Frazer.
- 5 . Please remove your A/C prior to remount delivery at Frazer.
- 6 . To minimize delays, customer provided items should be present prior to unit production start.
- 7 . Per TMVCC we are quoting this through our licensed franchise dealer, Knapp Chevrolet.
- 8 . Please make your purchase order out to Knapp Chevrolet (P.O. Box 4179, Houston, TX 77210). Please email a copy of your purchase order and this quote to Bob Flanders with Knapp Chevrolet at bflanders@knappchevy.com and to Adam Fischer at sales@frazerbilt.com.
- 9 . Fair condition of module is assumed when quoting paint. Large or excessive dents, deep or excessive scratches and unforeseen body work will require a revision to the quoted paint price.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best regards,



Laura Richardson
Frazer, Ltd.

LGR KVG



October 6, 2016

Mr. Cory Matthews
EMS Chief
Bryan Fire Department
Email: cmatthews@bryantx.gov

Quote # 10606C

Chief Matthews,

Per your request we are quoting remounting and refurbishing of your Frazer Urban Command Vehicle, Q-1768, onto a 2016 Chevy C3500 Extended Cab 6.0 gasoline chassis. For your convenience all pricing has been itemized below.

Frazer 8' 9" Urban Command Vehicle (Q-1768)		
2016/2017 Chevrolet C3500 6.0L gasoline chassis, 60" CA Extended Cab 4x2, Single Rear wheel (Ordered White)	\$	36,500.00
Remount of Module (see Incl. items below)	\$	15,000.00
Chassis Exterior Upgrades	\$	15,050.00
Chassis Interior Upgrades	\$	21,625.00
Module Exterior Upgrades	\$	16,100.00
HGAC fee included on remount quote # 10780	\$	0.00
Total	\$	104,275.00

Items included in above total:

Chassis Exterior Upgrades:

- 1 . Items included in remount fee:
 - a) Ranch Hand powder coated grille guard \$ Incl.
 - b) (2) Whelen M6 red/clear split grille LEDs with clear lenses in lieu of standard M4 LEDs \$ 150.00
Layout: Red/Clear - Clear/Red
 - c) (2) Whelen M6 red/clear split intersect LEDs with clear lenses & 45 degree brackets in lieu of standard M4 LEDs \$ 150.00
Layout: Blue/Red - Red/Blue
 - d) (2) Whelen SA314B speakers in lieu of standard \$ 450.00
 - e) (2) Mega fuses with new wiring
 - f) New mounting rubber
 - g) New tie downs & spacers

- h) VHB Tape
- i) Furnish & install back-up alarm & kill relay for Chevy C3500

Note - install backup alarm kill relay

- j) Mud flaps
- k) This unit needs a state inspection
- l) Make old chassis road ready - customer will pick up (TBD)
 - 1. Install rear mud flaps on chassis
 - 2. Install rear BTT lights
 - 3. Reinstall existing air suspension compressor from front I/O onto old chassis
 - 4. Remove license plate on rear of module and keep with old chassis
- m) Fuel with gasoline to verify fuel flow
- n) Issue temporary license plate
- o) Wash Unit
- p) Unit will be picked up by the customer
- q) Stripe new chassis to match module
- r) Re-route chassis exhaust to exit under driver's side forward of the wheel well

2 . Furnish & install ArcRite running boards on chassis	\$	850.00
3 . Furnish & install Stainless steel wheel covers	\$	450.00
4 . Chassis has single color paint scheme; Candy Apple Red - FLNA 3047	\$	3,500.00
5 . Furnish & install Hella fog lights on the grille guard w/ switch on console	\$	400.00
6 . Furnish & install (2) extra Whelen M6 series red/amber split LEDs on front fenders (red to front)		500.00
7 . Furnish & install dual Buell 10" and 12" air horns through the front bumper, and compressor mounted in the electrical compartment	\$	1,700.00
<i>Note - install momentary switch on the console switch panel</i>		

8 . After market vinyl seats in truck cab- Pattern: Marlin, Color: MRL-3226 Blackbeard	\$	1,150.00
9 . 3M-GTT Opticom (latching) mounted to roof of truck cab - discuss switching	\$	2,000.00
10 . Furnish & install Whelen Freedom Series light bar (ID #27003) determine color layout & switching	\$	3,750.00
Total	\$	15,050.00

Chassis Interior Upgrades

11 . Furnish & install pinned powder coated aluminum six position console:	\$	Incl.
a) Slot 1 – Furnish & install MDT plate (extended) with holes moved as far forward and to the right as possible - no swivel - without a genset fuel gauge	\$	125.00
<i>Note - Remove and reinstall your Frazer swivel onto extended MDT plate - centered toward the rear</i>		

b) Slot 2 – Traffic advisor control head		
<i>Note - terminate to traffic advisor on rear wall of module</i>		
c) Slot 3 – Furnish & install Whelen 295HFSC9 siren in lieu of standard with Tap 2 w/ mic on P/S of console slot #2	\$	225.00
d) Slot 4 – Single Switch Panel		
Switch layout – Primary, Secondary, Side Scene, Side Scene, Front Scene, Fog Lights, Rear Load, AIR HORN, Blank		
e) Slot 5 - Radio plate 2398		
f) Slot 6 - Radio plate 2399		
12 . Furnish & install Havis docking station for Panasonic Toughbook laptops with power supply and dual high gain antenna, Lind power supply, Panasonic Toughbook CF-31 and CF-19 per customer provided quote Q-140353. (Note – drop ship computers directly to customer)	\$	12,500.00
13 . Furnish and install new Motorola VML 750 LTE modem behind passenger's seat in chassis cab - wire ignition hot	\$	2,500.00
<i>Note - Ship loose existing Gemini data radio & all wiring from electrical compartment</i>	\$	100.00
<i>Note - This device has three antennas that run to the roof and one Ethernet cable that run to the MDT docking station. It does not connect to the other router.</i>		
14 . Fabricate cover for wire harness going into console	\$	200.00
15 . Furnish & install (1) large aluminum map holder on rear of console	\$	175.00
16 . Remove & reinstall (2) Streamlight SL-20X LED flashlight chargers, one on each side of console towards the front at an angle	\$	150.00
Note - wired battery hot		
17 . Furnish & install Knox Key Secure w/ WiFi on floor in front of console towards D/S - facing up	\$	1,750.00
Note - wired battery hot		
18. Remove and re-install Motorola APX6500 self-contained radio in console slot 5	\$	350.00
a) Remove & reinstall speaker on chassis floor in front of console		
b) Remove & reinstall mic on driver side of slot 1		
c) Wire radio battery hot		
d) Remove & reinstall 800 Mhz antenna on module roof		
19. Furnish & install Motorola APX 4500 VHF self contained radio in console slot 6	\$	1,500.00
a) Furnish & install mic on D/S of slot 2		
b) Furnish & install VHF antenna on module roof		
c) Wire battery hot		
20 . Remove and reinstall Tremco anti-theft system in the chassis cab with foot switch under drivers side mat and the module under drivers side of dashboard	\$	400.00
21 . Remove Cradlepoint router from rear wall of chassis and reinstall on rear wall of new chassis behind driver seat, wire ignition hot	\$	400.00
22 . Furnish & install replacement rearview mirror with a built in 3.5" monitor	\$	1,050.00
23 . Remove & reinstall thermal imaging camera charger under the seat in the back	\$	200.00
Note - wire battery hot		
Total	\$	21,625.00

Module Exterior Upgrades:

24 . Items included in remount fee:	\$	Incl.
a) Install new ignition & fail safe solenoids on electrical shelf		
b) Full electrical check		
Furnish & install (2) 4" round red LED lower B/T/T's and (2) 4" round lower clear back up		
c) lights		
d) Replace all door compartment bumpers		
e) Replace weather stripping		
f) New ribbed rubber in all applicable compartments		
g) Replace existing halogen compartment lights w/ LED flex strip lighting		
h) Ensure front wall is grounded		
i) This unit needs to be weighed and a weight slip provided to the customer		
j) Replace marker lights (discard old)		
k) Furnish & install wheel well guard		
l) Install new factory fuel guard (discard old)		
m) Frazer key fob		
25 . Striping & lettering to match existing fleet (See Kelly)	\$	2,650.00
26 . Conspicuity on the entire rear of the module in a chevron pattern; FLUORESCENT YELLOW/GREEN base - RED translucent overlay	\$	900.00
27 . Removal of existing conspicuity on rear of module	\$	600.00
28 . Furnish and install the following decals:	\$	Incl.
a) Install CO stickers in three (3) locations		
b) Install one (1) NO SMOKING sticker on dash and ship one (1) loose		
29 . Strip, prime, and repaint module Candy Apple Red - FLNA 3047	\$	7,500.00
a) Furnish & install painted corner caps on module		
b) Replace compartment and entry door latches (Eberhard)		

c) (5) J236 keys		
d) Ship loose all existing emergency lighting:		
e) Remove & reinstall roof mounted antennae's		
f) Furnish & install new doors, panels & hinges on all compartment doors		
30 . All clear lenses on Whelen LEDs	\$	incl.
31 . Furnish & install (4) Whelen M6 red LEDs w/ converter flanges on upper corners of driver's & passenger's sides	\$	1,000.00
32 . Furnish & install (2) Whelen M6 clear LEDs w/ converter flanges on upper corners of rear wall	\$	500.00
33 . Furnish & install (2) Whelen M6 amber LEDs w/ converter flanges on rear wall (lower position)	\$	500.00
34 . Furnish & install (4) TIR 3 LED's on treadbrite above the wheel well; (2) on driver's side & (2) on passenger's side	\$	1,000.00
35 . Furnish & install (2) Whelen Pioneer SlimLine side scene lights mounted on sides of module on (2) switches, plate over existing side scene lights as necessary	\$	4,000.00
36 . Furnish & install new traffic advisor with control head in console	\$	1,400.00
37 . Replace license plate holder w/ new Cast LED license plate holder	\$	50.00
38 . Furnish & install new Meltric single 30A twist lock shore power receptacle on driver's side front corner w/ pigtail shipped loose, (discard existing)	\$	800.00
39 . Furnish & install shore power ignition kill switch	\$	450.00
40 . Furnish & install treadbrite for the following (discard old):	\$	850.00
a) Driver's & Passenger's side front corner panels		
b) Passenger's side wheel well panel		
c) Driver's side wheel well panel (1) square filler guard		
d) Driver side rear panel with (2) 4" round light cut outs		
e) Passenger side rear panel with (2) 4" round light cut outs		
41 . Replace entire rear bumper (discard existing)	\$	850.00
a) Driver side bumper cap		
b) Center step		
c) Passenger side bumper cap		
d) Driver & passenger side dock bumper		
e) Center bumper strip		
42 . Furnish & install Voyager back up camera on the rear wall	\$	550.00

43 . Furnish & install new Lambda power supply (discard existing)	\$	1,350.00
44 . Relocate fuel fill on D/S to the second compartment on the D/S on the floor towards the front wall insert	\$	2,800.00
a) Furnish & install door & insert to reconfigure D/S front compartment		
b) Furnish & install LED flex strip lighting (run new wiring)		
c) Lower shelf approximately 5" to allow room for backboard storage		
	Total \$	16,100.00

Terms and Conditions

- 1 . Quote valid for 90 days.
- 2 . All pricing is F.O.B Houston.
- 3 . Payment for the entire purchase is due upon receipt & acceptance of your completed unit.
- 4 . To minimize delays, customer provided items should be present prior to unit production start.
- 5 . Per TMVCC we are quoting this through our licensed franchise dealer, Knapp Chevrolet.
- 6 . Please make your purchase order out to Knapp Chevrolet (P.O. Box 4179, Houston, TX 77210). Please email a copy of your purchase order and this quote to Bob Flanders with Knapp Chevrolet at bflanders@knappchevy.com and to Adam Fischer at sales@frazerbilt.com.
- 7 . Fair condition of module is assumed when quoting paint. Large or excessive dents, deep or excessive scratches and unforeseen body work will require a revision to the quoted paint price.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Laura Richardson
Frazer, Ltd.

LGR:EF