



October 9, 2015

Mr. Cory Matthews
 EMS Chief
 Bryan Fire Department
 Email: cmatthews@bryantx.gov

Quote #9726B

Chief Matthews,

Per your request we are quoting remounting and refurbishing your Frazer Type I 12' 4" Taller Generator Powered Module, E-1861, onto a Chevrolet C3500 6.0L gasoline chassis with a Granning air suspension system. For your convenience all pricing has been itemized below.

2015/16 Chevrolet C3500 6.0L gasoline chassis (ordered red)	\$ 34,500.00
Granning Air Suspension System	\$ 6,700.00
Remount of Module (see Incl. Items below)	\$ 15,000.00
Chassis Exterior Upgrades	\$ 5,750.00
Chassis Interior Upgrades	\$ 26,225.00
Module Exterior Upgrades	\$ 42,900.00
Module Interior Upgrades	\$ 33,950.00
HGAC	\$ 600.00
Total	\$ 165,625.00

Items included in above total:

Chassis Exterior Upgrades:

1. Items included in remount fee:
 - a) Ranch Hand powder coated grille guard \$ incl.
 - b) (2) Whelen M6 split grille lights w/ clear lenses in lieu of standard \$ 150.00
Layout: red/clear, clear/red
 - c) (2) Whelen M6 split intersects w/ clear lenses in lieu of standard \$ 150.00
Layout: blue/red, red/blue
 - d) (2) Whelen SA314B speakers in lieu of standard \$ 450.00
 - e) Frazer aluminum rear window pass through plate \$ incl.
 - f) (2) mega fuses with new wiring \$ incl.
 - g) Stripe new chassis to match module \$ incl.
 - h) New mounting rubber \$ incl.
 - i) Make old chassis road ready, if applicable \$ incl.
 1. Install rear mud flaps on chassis \$ incl.
 2. Install rear BTT lights \$ incl.
 3. Remove and reinstall compressor on chassis, if applicable \$ incl.
2. Furnish & install Per-Lux fog lights centered on grill guard \$ 350.00

3. Furnish & install (2) extra Whelen M6 series red/amber split LEDs on front fenders	\$	600.00
4. Furnish & install dual Buell 10" and 12" air horns through the front bumper with momentary switch at the console, and compressor mounted in the electrical compartment (ID#7654, 7655, 18957, 2627, 29614, 29615) Note – install switch on blank space forward of the sired to the left of the MDT swivel.	\$	1,700.00
5. Install stainless steel wheel covers in lieu of factory wheel covers (ID#20852)	\$	350.00
6. Re-route chassis exhaust to exit under long lower storage compartment	\$	incl.
7. Recover factory seats with premium vinyl to match chassis factory color scheme	\$	1,150.00
8. Furnish & install ArcRite running boards on chassis	\$	850.00
Total	\$	5,750.00

Chassis Interior Upgrades

9. Items included in remount fee:		
a) Furnish & install pinned powder coated aluminum six position console	\$	incl.
b) Furnish & install Whelen 295HFSC9 siren in lieu of standard with TAP2	\$	225.00
10. Front of Console –	\$	incl.
11. Slot 1 – Extended MDT plate		
12. Slot 2 – Traffic Advisor control head		
13. Slot 3 – Siren		
14. Slot 4 – Single switch panel		
Switch layout – Primary, Secondary, Side Scene, Side Scene, Front Scene, Fog Lights, Rear Load, Interior Lights, Start/Stop		
15. Slot 5 – VHF Radio		
16. Slot 6 – Radio		
17. Rear of Console – Furnish and install large map holder on the rear of console in lieu of dual map holder per the new configuration of 2015 Chevy chassis	\$	175.00
18. Furnish & install Autovision rearview mirror with built in 3.5" RCD monitor, and terminate wiring to existing rear view back up camera	\$	1,050.00
19. Remove and reinstall (2) high glove box holder on rear wall of truck cab	\$	25.00
20. Remove and reinstall your Frazer swivel onto a new extended MDT plate, hardwire your existing power supply battery hot	\$	225.00
21. Furnish & install TAM85 Traffic Advisor control head, terminate to Traffic Advisor bar on rear wall of module	\$	1,400.00
22. Remove and reinstall (2) Streamlight SL-20X LED flashlights with chargers, one on each side of console	\$	175.00
23. Remove and reinstall your Knox key secure in same location in new chassis cab, wire battery hot (customer to provide removal key loose at time of drop off)	\$	175.00
24. Furnish and install a Motorola remote mount radio head package APX6500-HCM2 in module to include: (1) remote mount head at the console with the speaker mounted on floor in front of console, (1) remote mount head at the action wall with speaker on stainless at front of action wall, (1) GPS antenna on roof of chassis (discuss this), (1) dual band antenna on roof of chassis (discuss this), and run new coax to both antennas, (per customer provided quote)	\$	5,225.00
Discuss this prior to ordering – BFD may be changing radios		
25. Remove and reinstall existing antennae on module roof.	\$	incl.
26. Remove and reinstall Tremco anti-theft system in the chassis cab with foot switch under drivers side mat and the module under drivers side of dashboard	\$	400.00

27 . Furnish & install Gemini PD+ data radio with base in electrical compartment, run coax to chassis roof, and install antenna (Per customer provided quote #57839 by ProComm Alaska) (ship existing data radio loose) Discuss this prior to ordering – BFD may be changing radios	\$	4,900.00
28 . Furnish & install Havis docking station for Panasonic Toughbook laptops with power supply and dual high gain antenna, Lind power supply, Panasonic Toughbook CF-31 and CF-19 per customer provided quote Q-140353. (Note – drop ship computers directly to customer)	\$	12,250.00
Total	\$	26,225.00

Module Exterior Upgrades

29 . Items included in remount fee:		
a) Install new ignition & fail safe solenoids on electrical shelf	\$	incl.
b) Full electrical check	\$	incl.
c) Generator system check and inspect all generator cabling, replace as needed	\$	incl.
d) Terminate existing Onan buzzer kill switch to new chassis (if available)	\$	incl.
e) Rewire tail lights	\$	incl.
f) New passthrough rubber boot	\$	incl.
g) Replace all door compartment bumpers	\$	incl.
h) Replace weather stripping	\$	incl.
i) Add new insulation to side & rear entry doors, if applicable	\$	incl.
j) Replace entry door windows with double pane windows, if applicable	\$	incl.
k) New ribbed rubber in compartments, in applicable	\$	incl.
l) Replace all halogen compartment lights	\$	incl.
m) Time save exterior compartment panels, if applicable Note – Conspicuity strips will be lost with this process	\$	incl.
30 . Strip, prime, and repaint 12'4" module Chevy red to match chassis Note – Items sub-listed are included with paint unless stated other wise	\$	6,900.00
a) Furnish & install painted corner caps on module	\$	incl.
b) Replace compartment and entry door latches Note – Check latch keying number and also if unit has electric latches	\$	N/C
c) Replace marker lights	\$	incl.
d) Remove & reinstall rear bumper	\$	incl.
e) Remove & reinstall treadbrite panels	\$	incl.
f) Remove and ship loose all listed emergency lighting below:	\$	incl.
Remove (8) 600 series red corner box lights	\$	incl.
Remove (5) 600 series front wall ligs	\$	incl.
Remove (4) 600 series rear wall lights	\$	incl.
Remove (1) 508 series rear load lights	\$	incl.
Remove (2) 600 series rear red BTT	\$	incl.
Remove (2) 700 series wheel well LEDs	\$	incl.
Remove (2) 250 watt Kwik-Raze side scene light	\$	incl.
31 . Removal of existing conspicuity prior to painting	\$	750.00
32 . Striping & lettering to match last unit (X-969) ⁵	\$	2,700.00
33 . 3M diamond grade fluorescent lime yellow conspicuity with translucent red overlay on entire rear of module including rear entry doors	\$	1,500.00
34 . Add 4" 3M diamond grade white conspicuity strips to the interior panels of all applicable compartment and entry doors	\$	175.00

35 . All emergency lighting will be replaced in existing locations with the exception of rear lower emergency lights, which will shift downward on plating from A/C retrofit.		
36 . Furnish & install Whelen Pioneer Plus dual panel Super-LED floodlight on the front wall with ON/OFF switch at the console (ID#18139, 18140, 18472) Note – install switch in blank space on single switch panel	\$	1,750.00
37 . Clear lenses on listed emergency lights (If customer is getting clear lenses)		
38 . Furnish & install (8) Whelen M9 series red LEDs corner box lights w/converter flange	\$	2,400.00
39 . Furnish & install (5) Whelen M6 series LEDs on front wall w/converter flanges <i>Front Layout: blue, red, clear, red, blue</i>	\$	1,125.00
40 . Furnish & install (4) Whelen M6 series LEDs on rear wall w/converter flanges <i>Rear layout: red/blue, amber, amber, blue/red</i>	\$	1,000.00
41 . Furnish & install (1) Whelen M6 series Gradient LED load light w/converter flange on rear of module, wired with two switches, one at the console, one at the rear doors.	\$	375.00
42 . Furnish & install (2) Whelen M6 series red B/T/T w converter flanges	\$	350.00
43 . Furnish & install (2) Whelen M7 wheel well LEDs w/converter flanges	\$	600.00
44 . Furnish & install (2) FRC Spectra 900 series LED side scene lights, wired to 2 switches	\$	1,500.00
45 . Furnish & install Voyager rear view camera above rear entry doors in standard location, terminate cable to monitor in rearview mirror in chassis cab	\$	550.00
46 . Furnish & install Traffic Advisor light bar on rear of module	\$	incl.
47 . Replace 30amp shore power receptacle with new twist lock style with pigtail adapter shipped loose	\$	225.00
48 . Remove raised floor of the rear storage compartment (from split system A/C), and make floor flat	\$	600.00
49 . Furnish & install 1"x2" angle on the roof of the rear storage compartment with (2) double coat hooks, remove (1) coat hook on the rear wall and (1) on the front wall below the ceiling angle	\$	150.00
50 . Remove & reinstall your SCBA brackets in the rear storage compartment and mounted on plates in the back corners of the compartment, 10" off the floor of the compartment. Plates should be installed at 45 degrees in the back corners of the compartment	\$	550.00
51 . Terminate existing shore power kill switch to new chassis	\$	incl.
52 . Replace treadbrite on front corners, wheel wells, and rear of module, discard existing	\$	825.00
53 . Remove and replace existing back up lamps and rear B/T/T signals with new LED 4" round fixtures mounted in the treadbrite	\$	425.00
54 . Replace entire rear bumper, discard existing	\$	850.00
55 . Furnish & install new rear entry door grabbers (discard existing)	\$	50.00
56 . Furnish & install cast LED license plate light (discard existing)	\$	50.00
57 . Furnish & install new Onan 5.5kW generator with non permeable hoses, emissions canister kit and add new Chevy 10gal fuel tank and fuel pump, reuse existing exterior door Note – Please remove your Onan generator prior to remount delivery at Frazer.	\$	5,000.00
58 . Furnish & install (2) Scott Air-Pak's AP-75, Head harness, voice amplifier, and carbon cylinder per customer provided quote 82610-0. (Note – DROP SHIP items directly to customer)	\$	12,500.00
	Total \$	42,900.00

Module Interior Upgrades:

59 . Items included in remount fee:	\$	incl.
a) Reattach cushion seat magnets, if applicable	\$	incl.
b) Replace all non-skid material on threshold(s) with 3M non-skid material	\$	incl.
c) Complete detail of module interior	\$	incl.
Clean & wipe down lasco walls	\$	incl.
Clean & wipe down floor of module	\$	incl.
Clean & wipe down exterior & interior of cabinets	\$	incl.
Clean & wipe down compartments and shelves	\$	incl.
60 . Modify the front I/O so AutoPulse device can be stored on its end, cut down shelf and add vertical divider	\$	650.00
61 . Replace Lonseal vinyl on existing Alucabond sub-floor with Lonseal Lonplate II (gunmetal color), reuse existing powder coated aluminum O2 box, replace thresholds and add non-skid tape on top	\$	2,850.00
62 . Replace ribbed rubber on shelf and floor of front I/O (discard existing)	\$	50.00
63 . Furnish and install new ash grey Wise soft cushion captains chair with built in child's safety and 3pt harness (ID#28065) (ship existing chair loose)	\$	1,325.00
64 . Furnish & install new ash grey Wise trim only on the squad bench cabinet, action wall cabinet, front wall cabinet, and front I/O, will not be installed on the countertops due to thin lip	\$	175.00
65 . Remove and reinstall 2 high "D" cylinder holder in front I/O facing rear (with floor replacement) in new location toward the passengers side so that there is ~6" of clearance from the insert for the roll up door to the side of the cylinder holder, install flat head screws in old holes in floor	\$	150.00
66 . Replace air conditioner w/ new Dometic self-contained A/C unit including breathe easy plenum with germicidal UV light protection compartment and relocate thermostat to action wall (ship loose or discard) ⁵ Note – Please remove A/C prior to delivery of remount to Frazer. This includes making necessary modifications not limited to: Interior – walls, register, and vents Exterior – relocation of (2) emergency rear lights with painted A/C retrofit plating, installation of a new style A/C vent, furnish new vented style A/C door (if needed)	\$	5,500.00
67 . Furnish & ship loose (1) Zoll Autopulse with 2 year extended warranty as requested by customer through quote #160846v:1 (estimated pricing based upon projected pricing increases by manufacturer)	\$	18,800.00
68 . Furnish & ship loose AutoVent 3000 with carrying case	\$	4,450.00
	Total \$	33,950.00

Terms and Conditions

- 1 . This quote is valid for 90 days.
- 2 . All pricing is F.O.B. Houston.
- 3 . Please note, payment for the entire purchase is due upon receipt and acceptance of completed unit.
- 4 . Per TMVCC we are quoting this through our licensed franchise dealer Knapp Chevrolet.

Please make your purchase order out to Knapp Chevrolet (P.O. Box 4179, Houston, TX 77210). Please email a copy of your purchase order and this quote to Bob Flanders with Knapp Chevrolet bflanders@knappchevy.com and to Adam Fischer at sales@frazerbilt.com.

- 5 . To minimize delays, customer provided items must be present 30 day prior to unit production start.

- 6 . Please remove your A/C prior to remount delivery at Frazer.
- 7 . Please remove your Onan generator prior to remount delivery at Frazer.
- 8 . Fair condition of module is assumed when quoting paint. Large or excessive dents, deep or excessive scratches and unforeseen body work will require a revision to the quoted paint price.
- 9 . *Striping and lettering pricing may be adjusted based on the company's scheme. Striping and lettering pricing includes two hours' design time in the base price. Additional design time for more extensive graphics and/or multiple changes is quoted at \$100/hour.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Laura Richardson
Frazer, Ltd.

LGR:AF